

Name of School: RAMLAL PAUL HIGHER SECONDARY SCHOOL

A. Works approved by PAB (2018-19) under Samagra Shiksha:

Sl. No.	Name of Work	Unit Cost (Rs. in Lakh)	Nos.	Sanction Amount (Rs. in Lakh)
1	Nil			
Total				

B. Works approved by PAB (2019-20) under Samagra Shiksha:

Sl. No.	Name of Work	Unit Cost (Rs. in Lakh)	Nos.	Sanction Amount (Rs. in Lakh)
1	Classroom	18.68	3	56.04
Total				56.04

C. Works to be taken-up under School Fagathansi Mission (2019-20):

I. Major Repairing		
i	Name of Work	Major Repair of existing rooms
ii	Description of Works	School has proposed for repairing of 35 (thirty five) existing rooms. The items of work to be repaired are as following: <ul style="list-style-type: none">• Cement Concrete flooring for 35 (thirty five) rooms• Ceiling for 17 (seventeen) rooms• Roofing for 17 (seventeen) rooms• Doors & Windows for 35 (thirty five) rooms• Painting for 21 (twenty one) rooms
iii	Estimated Cost (Rs. in Lakh)	Flooring = Rs. 16.443 Lakh Ceiling = Rs. 9.917 Lakh Roofing = Rs. 2.149 Lakh Doors & Windows = Rs. 16.597 Lakh <u>Paintings = Rs. 5.142 Lakh</u> Total = Rs. 50.248 Lakh

Total of C = Rs. 50.248 Lakh