

**Name of School: MALOM MEGHA HIGH SCHOOL**

A. Works approved by PAB (2018-19) under Samagra Shiksha:

Sl. No.	Name of Work	Unit Cost (Rs. in Lakh)	Nos.	Sanction Amount (Rs. in Lakh)
1	Major Repair	4.027	-	4.027
<b>Total</b>				<b>4.027</b>

B. Works approved by PAB (2019-20) under Samagra Shiksha:

Sl. No.	Name of Work	Unit Cost (Rs. in Lakh)	Nos.	Sanction Amount (Rs. in Lakh)
1	Science Laboratory	16.5	1	16.5
<b>Total</b>				<b>16.5</b>

C. Works to be taken-up under School Fagathansi Mission (2019-20):

<b>I. Construction of Library Room</b>		
i	Name of Work	Construction of 1 (one) Library Room
ii	Description of Works	School has 1(one) old Library room of semi pucca structure which is not repairable. The same need to be dismantled and reconstruction of new one is required. In the same line, the school has propose for construction of 1 (one) new library room.
iii	Estimated Cost (Rs. in Lakh)	Rs. 15.58 Lakh
<b>II. Construction of Computer Room</b>		
i	Name of Work	Construction of 1 (one) Computer Room
ii	Description of Works	School has 1(one) old Computer room of semi pucca structure which is not repairable. The same need to be dismantled and reconstruction of new one is required. In the same line, the school has propose for construction of 1 (one) new Computer room.
iii	Estimated Cost (Rs. in Lakh)	Rs. 21.78 Lakh
<b>III. Construction of Laboratory Room</b>		
i	Name of Work	Construction of 1 (one) Laboratory
ii	Description of Works	School has propose for construction of 1(one) new Laboratory room. However, construction 1 (one) science laboratory (at the unit cost of Rs. 16.5 Lakh) has been considered to sanction/approve in PAB 2019-20 under Samagra Shiksha. This will meet the propose requirement.
iii	Estimated Cost (Rs. in Lakh)	Nil

<b>IV. Construction of Classrooms</b>		
i	Name of Work	Construction of 3 (three) classrooms
ii	Description of Works	School has propose for construction of 3 (three) new classrooms thereby dismantling the old semi pucca classrooms which are in pathetic condition and non repairable.
iii	Estimated Cost (Rs. in Lakh)	3 (three) classrooms x Rs. 16.98 Lakh = Rs. 50.94 Lakh
<b>V. Major Repairing</b>		
i	Name of Work	Major Repair for 6 (six) existing classrooms
ii	Description of Works	School has proposed for repairing of 6 (six) existing classrooms. The items of work to be repaired are as following: <ul style="list-style-type: none"> <li>• Roofing</li> <li>• Cement Concrete flooring</li> <li>• Ceiling with frames</li> <li>• Plastering &amp; Painting</li> <li>• Doors &amp; Windows</li> </ul>
iii	Estimated Cost (Rs. in Lakh)	Flooring = Rs. 6.516 Lakh Ceiling = Rs. 6.63 Lakh Roofing = Rs. 1.684 Lakh Plastering & Painting = Rs. 4.253 Lakh <u>Doors &amp; Windows = Rs. 2.94 Lakh</u> Total = Rs. 22.023 Lakh

**Total of C = Rs. 110.323 Lakh**